API_WELLNO	TYP_INSP	INSP_PURPOSE	DT_INSPTD	DT_REMDYRQ	VON_TO	TYPENOTIFICATION	DT_PASSED	CMMNT	DT_MOD
34009227040000	SW			13-Jun-87	03-Jun-87			1501:9-3-07(E)(F)	03-May-00
34009227040000	SW			24-Sep-87	14-Sep-87		26-Oct-87	1501:9-3-07 (E)(F)	03-May-00
34009227040000	SW			22-Mar-87	09-Mar-87		06-Oct-87	ACTION Legal 1501:9-3-07 (E)(F) Memo to Ralph M.	03-May-00
34009227040000	SW	SC	14-Dec-00		14-Dec-00	LET		THIS WELL IS IDLE AND INCAPABLE OF INJECTING BRINE. THIS IS NO PRESSURE ON THE INJEC. OR ANNULUS OF WELL, WEEDS ARE GROWING UP IN THE STORAGE PIT AREA. POOR EQUIPMENT AT SITE, TALKED TO LEO ALTIER, HE SAID WELL WAS GOING TO SOLD AT THE SHERIFF'S OFF	14-Dec-00
34009227040000	SW	sc	14-Dec-00		14-Dec-00	LET	22-Mar-01	FOLLOW UP TO NOV # 1269i209 THIS WELL IS IDLE AND INCAPABLE OF INJECTING BRINE. THIS IS NO PRESSURE ON THE INJEC. OR ANNULUS OF WELL, WEEDS ARE GROWING UP IN THE STORAGE PIT AREA. POOR EQUIPMENT AT SITE, TALKED TO LEO ALTIER, HE SAID WELL WAS GOIN	23-Mar-04
34009227040000	SW	SC	31-May-01	30-Jun-01	31-May-01	NOV	05-Sep-01	An inspection revealed the 1/4" valve at the well on the injection side is in non working condition, the valve needs to be replaced.	31-May-01

								,	
34009227040000	SW	SC	31-May-01	30-Jun-01	31-May-01	NOV	05-Sep-01	FOLLOW UP TO NOV # 5609i205 An inspection revealed the 1/4" valve at the well on the injection side is in non working condition, the valve needs to be replaced. 1509.03 AND 1501:9-3-05(A)(3) - VALVE NEEDS	05-Jan-04
34009227040000	SW				31-May-01		05-Sep-01	REPLACED	13-Jun-01
34009227040000	SW	NOV	12-Jul-01			FVI		Folloe - up on N.O.V., Non - Compliance, 1/4" valve has not been replaced or repaired on the injection side of the line at the well head. Also there is some oily soil that needs cleaned up below storage impoundment.	12-Jul-01
34003227040000		NO V	12 341 01					An inspection of the well revealed that the pressure on the injection and annulus stillthe same, 85 lbs. Last inspection both sides where 40 lbs. Need a mini test done on this well.	12 301 01
34009227040000	SW	SC	22-Jan-02	25-Feb-02	22-Jan-02	NOV	01-May-02	John Puterbaugh, also on site.	23-Jan-02
								FOLLOW UP TO NOV # 1269i707 An inspection of the well revealed that the pressure on the injection and annulus stillthe same, 85 lbs. Last inspection both sides where 40 lbs. Need a mini test done on this well.	
34009227040000	SW	SC	22-Jan-02	25-Feb-02	22-Jan-02	NOV	14-May-03	John Puterbaugh, also on site.	05-Jan-04
								An inspection of the well revealed some oily soil around a storage tank and below the storage impoudment, and a bare area below the well. NEED TO CLEAN UP ALL OILY SOIL AROUND TANK, AND STORAGE IMPOUNDMENT. SEED, MULCH, AND LIME	
34009227040000	SW	SC	07-Mar-02	08-Apr-02	07-Mar-02	NOV	01-May-02	BARE AREA BELOW WELL, ON	07-Mar-02

-									
34009227040000	SW	SC	07-Mar-02	08-Apr-02	07-Mar-02	NOV	14-May-03	FOLLOW UP TO NOV # 1269i854 An inspection of the well revealed some oily soil around a storage tank and below the storage impoudment, and a bare area below the well. NEED TO CLEAN UP ALL OILY SOIL AROUND TANK, AND STORAGE IMPOUNDMENT. SEED, MULCH, AND	05-Jan-04
34009227040000	SW	NOV	22-Apr-02				22-Apr-02	Follow-up on NOV, In-Compliance.	23-Apr-02
34009227040000	SW	SC	03-Jun-02				03-Jun-02	Checked injection well, no violations.	03-Jun-02
								Injection pressure on well, annulus side 10 lbs, injection side 20 lbs. There are some filters by pump that need to be hauled out and removed from site. Need to add some pressure on	
34009227040000	SW	SC	30-Jul-02				30-Jul-02	annulus side of well.	16-Oct-02
34009227040000	SW	SC	01-Oct-02				01-Oct-02	No violations.	01-Oct-02
34009227040000	SW	SC	13-Nov-02				13-Nov-02	No violations at this time.	13-Nov-02
34009227040000	SW	SC	06-Feb-03				06-Feb-03	No violations at this time.	13-Feb-03
34009227040000	SW	SC	17-Mar-03				17-Mar-03	No violations at this time.	21-Mar-03
34009227040000	SW	SC	22-Apr-03				22-Apr-03	No violations, county has dug a ditch across the lease rd., at this time there is no way of hauling brine into this site.	23-Apr-03
34009227040000	SW	SC	08-May-03	09-Jun-03	08-May-03	NOV	14-May-03	An inspection of the well site revealed a ditch cut across the lease rd., no way of entering and unloading brine for disposal. Well appears to be idle at this time. A M.I.T. test needs to be done on this well also. CALLED MR. CARPER ABOUT VIOLATIONS HE S	12-May-03

						1			
								FOLLOW UP TO NOV # 2113127346 An inspection of the well site revealed a ditch cut across the lease rd., no way of entering and unloading brine for disposal. Well appears to be idle at this time. A M.I.T. test needs to be	
34009227040000	sw	sc	08-May-03	09-Jun-03	08-May-03	NOV	14-May-03	done on this well also. CALLED	05-Jan-04
34009227040000	SW	NVF	14-May-03		, ,		· · · · · ·	Follow-up on NOV, In-Compliance.	19-May-03
34009227040000	SW	SC	, 16-Jul-03					No violations at the time of inspection.	04-Feb-04
34009227040000	SW	SC	18-Sep-03					No violations at the time of inspection.	29-Sep-03
34009227040000	SW	SC	18-Dec-03					No violations at the time of inspection.	04-Feb-04
34009227040000	SW	SC	11-Feb-04				11-Feb-04	No violations at the time of inspection.	08-Mar-04
								No violations at the time of inspection.	
								Updated coordinates, which were off	
34009227040000	SW	SC	10-Mar-04				10-Mar-04	significantly.	14-Apr-04
34009227040000	SW	SC	14-Apr-04				14-Apr-04	No violations at the time of inspection.	14-Apr-04
34009227040000	SW	SC	05-May-04				05-May-04	No violations at the time of inspection.	11-May-04
34009227040000	SW	SC	17-Jun-04				17-Jun-04	No violations at the time of inspection.	07-Jul-04
								Fluid level, in the pit, approx. 1 1/2 feet below	
34009227040000	SW		15-Jul-04				17-Aug-04	the top. Slight vacuum on tubing.	23-Oct-09
34009227040000	SW	SC	17-Aug-04				17-Aug-04	No violations at this time.	09-Sep-04
								There were no violations at the time of	
34009227040000	SW	SC	08-Oct-04				08-Oct-04	inspection.	10-Dec-04
34009227040000	SW	SC	12-Jan-05				12-Jan-05	The pit appears to have been recently pumped down. The fluid level is 1.5 ft from the top.	18-Jan-05
34009227040000		SC	09-May-05	16-Jun-05	16-May-05	NOV		The fluid level was 4 inches from the top of the storage pit. The well needs tested.	23-Oct-09
34009227040000	SW	SC	16-Sep-05					Well needs tested.	23-Oct-09
34009227040000	SW	NVF	04-Oct-05				30-Jun-08	No action was taken to test the well.	23-Oct-09
								Pit was found completely full. Called operator (4/4/06) and instructed him to take a load out	
34009227040000	SW	SC	04-Apr-06		04-Apr-06	PHN	30-Jun-08	of the pit ASAP.	23-Oct-09

						The fluid level was about a foot below the top of the pit.	
24000227040000	CVA	NI) /F	05 4 7 7 06	10 Am 00	20 1 00	The well needs a MIT. Suspension order was	33 O -+ 00
34009227040000	SW	NVF	05-Apr-06	18-Apr-06	30-Jun-08	issued 4/18/06.	23-Oct-09
24000227040000	CVA	OF	21 Apr 06		20 Jun 00	Accompanied Joe Hoerst, who took a sample	22 Oct 00
34009227040000	300	UF	21-Apr-06		30-Jun-08	of the pit water. Took water sample from frac tank. Prepared	23-Oct-09
24000227040000	CVA	0.5	27 Amr OC		20 1 00	·	33 O+ 00
34009227040000	SW	OF	27-Apr-06		30-Jun-08	sample for shipment.	23-Oct-09
24000227040000	C. A.	0.5	47.1406		20 1 00	Conditions are the same. No evidence of	22 0 -+ 00
34009227040000	SW	OF	17-May-06		30-Jun-08	recent activity.	23-Oct-09
						No college has been been deleged as a soul of the de-	
						No action has been taken to comply with the	
						Chief's Order. The fluid level in the pit was	
34009227040000	SW	OF	14-Jul-06		30-Jun-08	approximately 1 1/2 feet from the top.	23-Oct-09
34009227040000	SW	OF	14-Aug-06		30-Jun-08	No action has been taken to remedy violation.	23-Oct-09
						The pit was found full. Notified company. No	
34009227040000	SW	OF	19-Oct-06		30-Jun-08	action has been taken to comply with order.	23-Oct-09
						Fluid level in the pit was approximately a foot	
34009227040000	SW	OF	23-Oct-06			below the top.	23-Oct-09
34009227040000	SW	OF	15-Dec-06		30-Jun-08	No action has been taken to comply.	23-Oct-09
						Frac tank was removed. A couple truck loads	
						appear to have been taken from the pit. The	
34009227040000	SW	OF	21-Feb-07		30-Jun-08	well remains in noncompliance.	23-Oct-09
						There were no violations at the time of	
34009227040000	SW	OF	12-Apr-07		30-Jun-08	inspection.	23-Oct-09
						No action has been taken since last inspection.	
34009227040000	SW	OF	12-Jun-07		30-Jun-08	Accompanied by Joe Hoerst.	23-Oct-09
34009227040000	SW	OF	13-Jul-07		30-Jun-08	No action has been taken since last inspection.	23-Oct-09

				No action has been taken to plug or operate	
34009227040000	SW	OF	10-Sep-07	30-Jun-08 the well.	23-Oct-09
				The service rig was still on the well. No further	
				action appears to have been taken to plug the	
34009227040000	sw	OF	16-Jan-08	30-Jun-08 well.	23-Oct-09
34009227040000	SW	OF	27-Feb-08	30-Jun-08 Service rig was on the well.	23-Oct-09
				Rig and bulldozer were onsite. 1 1/2 inch	
34009227040000	SW	OF	10-Jun-08	30-Jun-08 tubing was on the trailer.	23-Oct-09
				Witnessed installation of the packer and	
34009227040000	SW	OF	17-Jun-08	30-Jun-08 tubing.	23-Oct-09
34009227040000	SW	OF	27-Jun-08	30-Jun-08 The well failed a pressure test.	06-Oct-08
34009227040000	SW	OF	30-Jun-08	30-Jun-08 The well passed a pressure test.	06-Oct-08
				No violations were found at the time of	
34009227040000	SW	sc	30-Sep-08	30-Sep-08 inspection.	06-Oct-08
				There were no violations found, at the time of	
34009227040000	SW	SC	03-Oct-08	03-Oct-08 inspection.	08-Apr-09
				There were no violations at the time of	
34009227040000	SW	SC	03-Dec-08	03-Dec-08 inspection.	08-Apr-09
				The pit was found completely full. Notified	
34009227040000	SW	SC	18-Feb-09	23-Feb-09 operator via telephone.	07-Apr-09
34009227040000	SW	NVF	23-Feb-09	23-Feb-09 The pit was pumped down.	07-Apr-09
34009227040000	SW	SC	12-Mar-09	12-Mar-09 The well was found without an ID.	08-Apr-09
				Inspection this day found a nicer, cleaner	
				facility than I am used to in Washington Co	
				my 1st visit. Found pump not running, tubing	
				on vacuum, 0# on annulus. Good ID's, said	
				they are using the well small to moderate	
34009227040000	SW	SC	09-Mar-10	amount. Fluid about 1/5' down fro	02-Dec-10
				Inspection this day found pump not running,	
				vacuum on tubing, 0# on annulus. Good ID's.	
34009227040000	SW	SC	24-Aug-10	Oil skim on water in dike area.	24-Aug-10

								Inspection this day found pump running,	
								tubing has 20#, 0# on annulus. Water storage	
								area/dike full but pump is running, should be	
34009227040000	sw	sc	17-Nov-10					lower. Good ID's.	17-Nov-10
34009227040000	SW	SC	03-Aug-11			FVI	03-Aug-11	No violations at this time.	08-Aug-11
								Company gauges had seized up and I was	
								unable to remove them for the test.	
								Company's gauges read 385 psi on annulus	
								and 30 psi on injection. The power had just	
								gone out there at the well and the operator	
								was concerned with getting the power back	
34009227040000	SW	SC	29-Nov-11				29-Nov-11	online.	29-Dec-11
								Pump was not running at time of inspection,	
								injection pressure was 10 psi. Unable to	
								inspect pressure on annulus because 1/4 inch	
								needle valve was corroded and unable to	
								accept gauge. Spoke with pump house	
								operator and asked to have valve replaced by	
34009227040000	SW	SC	20-Dec-11	21-Dec-11	20-Dec-11	FVI		12/	29-Dec-11
								Met Josh Garland at well site, checked	
								injection and annulus pressures on well. 1/4	
34009227040000	SW	R	05-Jan-12			FVI	05-Jan-12	nipple needs replaced on injection side of well.	18-Jan-12